

**Question 7.** *Provide the dates of scrubber wall ring installation (referred to in the response to the EPA's original September 28, 2010 CAA Section 114 request) and dates of scrubber system performance evaluation or testing before and after the installation of the rings for Units 1 & 2 at the facility.*

**Response:**

According to the original construction timeline, the scrubber wall rings were to be installed according the following schedule:

Unit 1 Module 1A	03/2003
Unit 1 Module 1B	09/2001
Unit 1 Module 1C	11/2003
Unit 1 Module 1D	05/2003
Unit 1 Module 1E	09/2003
Unit 1 Module 1F	01/2004
Unit 2 Module 1A	04/2002
Unit 2 Module 1B	06/2002
Unit 2 Module 1C	08/2002
Unit 2 Module 1D	11/2002
Unit 2 Module 1E	02/2002
Unit 2 Module 1F	01/2003

No testing was done prior to the installation of the wall rings for purposes of evaluating the wall rings' effect on scrubber system performance. Performance testing was done after the installation of the wall rings on Unit 1 Module 1B during the following months:

First Test	09/2001
Second Test	11/2001

This response was prepared by IPSC employee Jerry Hintze.